

QUALITY REMARK: AEPD
QUALITY REQUIREMENT NUMBER 443
MRB REPAIR
TYPE IV: REPAIR PROCEDURE FOR B50TF119 CLASS A, T-SLOTS.

SUPPLIER TO SUBMIT THE FOLLOWING TO PURCHASER IN
SHIPPING CONTAINER WITH PARTS PLUS DUPLICATE COPIES
UNDER SEPARATE MAILING TO APPROPRIATE GE CONTRACT ADMINISTRATOR

CERTIFICATE OF CONFORMANCE TO MRB REPAIR
AND ALL APPLICABLE SPECIFICATIONS REFERENCED
ON MRB REPAIR PROCEDURE AND PURCHASE ORDER.
SAID CERTIFICATE SHALL INCLUDE DOCUMENTATION THAT
PARTS WERE VISUALLY INSPECTED AND ACCEPTED BEFORE AND
AFTER SPRAY FOR CHIPPING, FLAKING, CRACKING,
OVERSPRAY, AND OTHER VISUAL DEFECTS.

DOCUMENTATION OF VERIFICATION OF COATING AFTER MACHINING
BY INSPECTION AND RESULTS OF BEND TEST OF TEST COUPONS.
NOTE: A TEST COUPON SHALL BE SPRAYED AND KEPT ON FILE
FOR BACK UP INFORMATION IN CASE COATING FAILS DURING MACHINING.

COPY OF MRB REPAIR PROCEDURE WITH SUPPLIER QUALITY INSPECTOR OR
REPRESENTATIVE SIGNATURE SIGN-OFF OR STAMP ON ALL
APPLICABLE ITEMS ON MRB REPAIR PROCEDURE
INDICATING COMPLETION OF AND COMPLIANCE TO ALL REQUIREMENTS.