


TrueChoice™ Material

Latest Repairs

GE's innovative repair services, part of our TrueChoice Material suite of offerings, help you maintain and extend engine performance – while boosting your bottom line with significant shop savings. By leveraging more than 100 years of innovation, our global network of technology, repair development and operations centers are at work every day developing new repairs to improve yield and decrease costs for our customers' fleets. In fact, each month we publish new repairs for our engine lines.



TrueChoice™ Material

Latest Repairs

Engine Model	Module Name	Component Code	Component Description	ATA	Repair Number	Repair Description	Repair Shop	PN Applicability
GENX-2B	HPT	513	Stage 1 HPT Nozzle	72-51-20	SB 72-0320	Alteration - Inner Platform Machining	Singapore Plant 23	2482M59G03 2482M59G04
GENX-2B	HPT	522	HPT Shroud Hanger - Stg 1	72-52-02	SB 72-0332	Hangers Alteration - Seal Slot, Cooling Hole, Pin Hole and Rope Seal	McAllen, Texas	2100M84G03 2100M84G04 2100M84G05
GENX-2B	LPT	582	Fan Mid Shaft	72-58-40	R014	Corrosion Shotpeen Repair of the Cone Body and Flange Area	Cincinnati, Ohio	
GENX-1B	HPT	513	Stage 1 HPT Nozzle	72-51-20	SB 72-0379	Alteration - Inner Platform Machining	Singapore Plant 23	2482M59G03 2482M59G04
GENX-1B	HPT	522	HPT Shroud Hanger - Stg 1	72-52-02	SB 72-0391	Hangers Alteration - Seal Slot, Cooling Hole, Pin Hole and Rope Seal	McAllen, Texas	2100M84G03 2100M84G04 2100M84G05
GENX-1B	LPT	582	Fan Mid Shaft	72-58-40	R014	Corrosion Shotpeen Repair of the Cone Body and Flange Area	Cincinnati, Ohio	
GE90	Fan	DBH3	Damper Brg Hsg No. 3	72-23-02	SPM 70-48-16	Replacement of Serrated Lock Ring Studs	Hungary	
CFM56-5B	Fan	215	Rear Spinner Cone	72-21-05	R025	Repair of the Spinner Rear Cone Surfaces that Mates with the Fan Blades, Fan Disk and Spinner Front Cone	Hungary	338-001-304-0 338-001-305-0
CF34-8E	Compressor	338	Compressor Discharge Rotating Seal	72-33-08	R002	Blend Repair	Cincinnati, Ohio	4129T28P05
CF34-8C	Compressor	338	Compressor Discharge Rotating Seal	72-33-08	R002	Blend Repair	Cincinnati, Ohio	4129T28P05
CF34-10E	Fan	238	Vane Assembly OGV Fan Stator	72-23-03	R001	Metal Leading Edge Replacement	Hungary	2032M97G02
CF34-10E	Fan	238	Vane Assembly OGV Fan Stator	72-23-03	R003	Platform Corner Crack Repair	Hungary	2032M97G02
CF34-10E	Fan	238	Vane Assembly OGV Fan Stator	72-23-03	R004	Leading and Trailing Edge Repair	Hungary	2032M97G02

Contacts

Europe

Kelly Cole
kelly.cole@ge.com

Kevin Nally
kevin.nally@ge.com

The Americas

Randy Harker
randy.harker@ge.com

Nate Bosco
nathan.bosco@ge.com

Asia

Joanne Chan
Joanne.Chan@ge.com

Ivan Phua
ivan.phua@ge.com

China

Katy Zhao
katy.zhao@ge.com

Yao Lu
Yao.Lu@ge.com

Africa

Kelly Cole
kelly.cole@ge.com

Middle East/Russia/CIS/Turkey

Rod Stratton
Rodrick.Stratton@ge.com

For more information, visit geaviation.com/truechoice, or go to myGEAviation.com to access parts and repair catalogs.



© 2018 GE. All rights reserved.
GE, the GE monogram, TrueChoice, CF34, GE90 and GENx are trademarks of GE. CFM56 is a trademark of CFM International, a 50/50 joint venture between GE and Safran Aircraft Engines.

AE-61548 (rev 04/18)
Printed in U.S.A.