

Technical Manual Index

CT7 TURBOSHAFT

CT7-2A/-2D/-2D1/-6/-6A/-8/-8A/-8A5/-8B/-8B5/-8E/-8E5/-8F/-8F5

Component Maintenance Manuals

November 1, 2008

The manuals are listed in publication number order.

The Rev. Cycle column indicates the following planned revision frequency for each publication listed:

90 - - - - - 90 day revision cycle (Quarterly updates)
180 - - - - - 180 day revision cycle (Semi-annual updates)

365 - - - - - 365 day revision cycle (Annual updates)
AR - - - - - As Required revision cycle

Publication Numbers with a (@) symbol in the Publication No. column indicates that the manual is a combined CT7 Turboshaft and Turboprop publication.

| <u>ATA Number</u> | <u>Publ. Number</u> | <u>Engine Model</u> | <u>Nomenclature</u> | <u>Part Number</u> | <u>VIN</u> | <u>OEM Name (Vendor Code)</u> | <u>Basic Issue Date</u> | <u>Rev. No.</u> | <u>Rev. Date</u> | <u>Rev. Cycle</u> |
|-------------------|--------------------------------------|---------------------|-----------------------------------|--|--|--|-------------------------|-----------------|------------------|-------------------|
| 72-60-00 | GEK 108722 formerly in SEI-573 | -2/-6 All | Particle Separator Blower | 6038T59P02 6038T59P04 | T20180-17 T20180-21 | Sundstrand Aerospace (99167) | 12/1/86 | 2 | 10/31/99 | AR |
| 73-13-00 | GEK 108723 formerly in SEI-573 | -2A | Sequence Valve | 6044T27G02 | - | GE Aircraft Engines (99207) | 9/1/86 | 2 | 10/31/99 | AR |
| 74-22-12 | GEK 108724 formerly in SEI-573 | -2 All | Electrical Control Unit | 4082T38G04 4082T38G07 4076T27G01 4076T27G02 | 7116M93G04 7116M93G06 7046M95G03 7046M95G04 | BAE Systems Controls (89954) formerly Lockheed Martin | 6/30/91 | 2 | 10/15/01 | AR |
| 74-23-00 | GEK 108725 formerly in SEI-573 | -2 All | Engine History Recorder | 4046T26G04 | 7084M83G02 | BAE Systems Controls (89954) formerly Lockheed Martin | 11/30/92 | 1 | 12/31/99 | AR |
| 75-11-00 | GEK 108726 formerly in SEI-573 | -2 All | Anti-icing Bleed & Start Valve | 5044T08P03 5044T08P05 5044T08P10 5044T08P11 | 73340-10 73340-12 73340-17 73340-18 | Vacco Industries (1PVC5) | 9/1/86 | 3 | 11/30/99 | AR |
| 75-31-01 | GEK 112188 | -8 All | Particle Separator Blower | 3062T06P03 | 4101412B | Hamilton Sundstrand (45153) | 3/1/04 | - | - | AR |

Technical Manual Index

CT7 TURBOSHAFT

Component Maintenance Manuals
November 1, 2008

| <u>ATA Number</u> | <u>Publ. Number</u> | <u>Engine Model</u> | <u>Nomenclature</u> | <u>Part Number</u> | <u>VIN</u> | <u>OEM Name (Vendor Code)</u> | <u>Basic Issue Date</u> | <u>Rev. No.</u> | <u>Rev. Date</u> | <u>Rev. Cycle</u> |
|-------------------|---|------------------------|--------------------------------|--|---|---|-------------------------|-----------------|------------------|-------------------|
| 74-20-02 | GEK 112189 | -8 All | Ignition Leads | 3060T08P01 3060T08P02 | 9059255-1 9059255-2 | Unison Industries (59501) | 3/1/04 | - | - | AR |
| 75-11-01 | GEK 112190 | -8 All | Anti Ice and Start Bleed Valve | 3062T13P02 3062T13P03 | C152510-2 C152510-3 | Microtechnica (A0076) | 5/15/06 | 1 | 7/31/07 | AR |
| 73-22-33 | GEK 112197 (Supplied by Hamilton Sundstrand) | -8 All | Electronic Engine Control | 4110T55P26 4110T55P27 4110T55P28 4110T55P29 4110T55P30 4110T55P31 4110T55P32 4110T55P34 4110T55P35 4110T55P36 4110T55P38 4110T55P43 | 819140-7-008 819140-7-007 819140-7-009 819140-4-008 819140-4-009 819140-4-011 819140-7-011 819140-7-010 819140-8-011 819140-8-010 819140-9-010 819140-10-014 | Hamilton Sundstrand (73030) | 6/1/05 | 1 | 3/15/08 | AR |
| 73-20-01 | GEK 112198 | -8 All | Fuel Metering Unit | 4110T52P10 | 819700-8 | Hamilton Sundstrand (73030) | 9/15/04 | - | - | AR |
| 79-20-07 | GEK 112199@ | -8 All CT7-9 All | Lube and Scavenge Pump | 3065T20P01 | 31-75107-3026-4 | Parker Hannifin Nichols Airborne Division (86329) | 8/31/04 | - | - | AR |
| 73-20-00 | SEI-573 | -2A | Hydromechanical Control Unit | 6038T62P09 6038T62P11 6038T62P13 6038T62P22 6038T62P24 | 763700-9 763700-11 763700-13 763700-32 763700-34 | Hamilton Sundstrand (73030) | 9/1/86 | 1 | 11/30/92 | AR |

Technical Manual Index

CT7 TURBOSHAFT

Component Maintenance Manuals
November 1, 2008

| ATA Number | Publ. Number | Engine Model | Nomenclature | Part Number | VIN | OEM Name (Vendor Code) | Basic Issue Date | Rev. No. | Rev. Date | Rev. Cycle |
|----------------------------------|-------------------------------------|--|------------------------------|--|--|---|---------------------------------|----------|-----------|------------|
| 73-10-01 Formerly 73-11-00 | SEI-650 @ formerly in SEI-573 | -2/-6 All CT7-5/- 7/ -9 All | Overspeed and Drain Valve | 6044T78G03 6044T78G04 | - | GE Aircraft Engines (99207) | 9/30/84 (Formerly 9/1/86) | 3 | 4/30/02 | AR |
| 79-20-06 formerly 79-22-00 | SEI-651@ formerly in SEI-573 | -2/-6 All CT7-5/- 7/ -9 All | Lube & Scavenge Pump | 5034T11P04 5034T11P05 | 31-75107-3010-4 (GD677-4) 31-75107-3022-4 (GD677-6) | Parker-Hannifin Corp., Nichols Aircraft Div. (86329) | 7/15/84 (formerly 9/1/86) | 3 | 6/30/00 | AR |
| 73-10-01 formerly 73-12-00 | SEI-652 @ formerly in SEI-573 | -2/-6/-8 All CT7-5/- 7/ -9 All | Fuel Boost Pump | 5034T91P06 | RR53150F | Crane Co. (Lear Romec Div.) (51663) | 9/30/84 (formerly 9/1/86) | 4 | 4/30/00 | AR |
| 79-21-01 formerly 79-21-02 | SEI-654 @ formerly in SEI-573 | -2/-6/-8 All CT7-5/- 7/ -9 All | Fuel/Oil Cooler | 5034T31P01 5034T31P02 5044T42P02 | UA536190-2 UA536190-3 UA537628-3 | Parker-Hannifin Corp., Aerospace Div. (78943) | 9/30/84 (formerly 9/1/86) | 2 | 6/30/00 | AR |
| 79-20-02 formerly 79-21-00 | SEI-665 @ formerly in SEI-573 | -2/-6/-8 All CT7-5/- 7/ -9 All | Fuel Cooled Oil Cooler | 6044T95P01 6044T95P02 | 735551A, 1B 735551C | Hamilton Sundstrand (73030) | 9/30/84 (formerly 9/1/86) | 3 | 5/31/00 | AR |

Questions or comments concerning the content of this index or changes in distribution should be directed to the GE – Aviation Customer Support Center. From within the United States, call toll-free 877-432-3272, FAX 877-432-3329. For International callers, dial 1-513-552-3272, FAX 1-513-552-3329. E-mail address is geae.csc@ae.ge.com.