





GE Aviation

# CF34-8E Turbofan Technical Manual Index – May 1, 2021 Engine Manual

GEK #	Engine Model	Nomenclature	Current Rev No.	Current Rev Date	Next Rev Date
108792	CF34 ALL	Standard Practices Manual GEK 9250 – <b>R110</b>	Ver 9.4	04/01/21	04/01/22
112030	CF34-8E	Engine Manuals Systems Description Section (SDS) GEK 112037 – <b>R8</b> Engine Manual (EM) GEK 112031 – <b>R42</b> Illustrated Parts Catalog (IPC) GEK 112032 – <b>R42</b> Illustrated Tooling and Equipment Manual (ITEM) GEK 105095 – <b>R41</b> Line Maintenance Manual (LMM) GEK 112031-1 – <b>R42</b> Model Photo Guide GEK 112035 – <b>R3</b> Service Bulletins (SB)	Ver 10.0	04/01/21	04/01/22



GE Aviation

## CF34-8E Turbofan Technical Manual Index – May 1, 2021 Supplementary Support Manuals

SUPPLEMENTARY SUPPORT MANUALS ARE AVAILABLE BY CONTACTING FLEET SUPPORT [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

GEK #	Engine Model	Nomenclature	Current Rev No.	Current Rev Date	Next Rev Date
112033	CF34-8E	Installation Manual	Rev 4	06/01/18	AR



GE Aviation

# CF34-8E Turbofan Technical Manual Index – May 1, 2021 General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
(SECTION)	CF34 ALL	GENERAL PRACTICES MANUAL SECTIONS		
73-10-00	CF34 ALL	General Information	10	08/18/17
73-10-16	CF34 ALL	Safety Instructions	6	03/24/11
73-10-19	CF34 ALL	Equivalent Tools, Materials, and Procedures	6	09/15/11
73-20-00	CF34 ALL	Soldering	6	11/17/11
73-20-02	CF34 ALL	Soldering and Desoldering Equipment Calibration	7	04/13/17
73-20-16	CF34 ALL	Circuit Card Assembly Soldering	7	04/11/17
73-20-17	CF34 ALL	Microcircuit Soldering	7	04/11/17
73-20-19	CF34 ALL	Terminal Connection	6	11/17/11
73-20-20	CF34 ALL	Hand Soldering	7	04/12/17
73-20-21	CF34 ALL	Manual Tinning Process	7	04/12/17
73-20-22	CF34 ALL	Surface Mounted Component Soldering	8	04/12/17



# CF34-8E Turbofan

## Technical Manual Index – May 1, 2021

### General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
73-20-23	CF34 ALL	Ball Grid Array Component Soldering <i>*This Section has been converted to Proprietary Practices and is no longer available. For information contact BAE Customer Service.</i>	8	06/07/19
73-30-00	CF34 ALL	General Repair	6	11/17/11
73-30-16	CF34 ALL	Identification Marking	9	06/03/20
73-30-17	CF34 ALL	Safety Wiring	6	11/17/11
73-30-19	CF34 ALL	Threaded Insert Repair	7	07/01/15
73-30-20	CF34 ALL	Out-of-Round Connector Repair	6	11/17/11
73-20-21	CF34 ALL	Potting of Connectors	6	11/17/11
73-30-24	CF34 ALL	Component Substitution	6	11/17/11
73-30-25	CF34 ALL	Chemical Thread-Locking	6	11/17/11
73-40-00	CF34 ALL	Circuit Card Assembly Repair	6	11/17/11



# CF34-8E Turbofan Technical Manual Index – May 1, 2021 General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
73-40-16	CF34 ALL	Part Removal	8	04/13/17
73-40-17	CF34 ALL	Part Installation	7	04/12/17
73-40-18	CF34 ALL	Part Replacement	8	04/13/17
73-40-19	CF34 ALL	General Laminate, Conductor Repair	10	09/11/18
73-40-20	CF34 ALL	Modification of Internal Circuits	6	11/17/11
73-40-21	CF34 ALL	Solder Mask Repair	7	10/08/18
73-40-22	CF34 ALL	ESD Label Replacement	6	11/17/11
73-40-23	CF34 ALL	Gold Pin Replacement	6	11/17/11
73-40-24	CF34 ALL	Terminal Strip Repair	6	11/17/11
73-45-00	CF34 ALL	Bonding and Encapsulating	6	11/17/11
73-45-16	CF34 ALL	Epoxy Bonding	7	06/27/13
73-45-17	CF34 ALL	Epoxy Bonding (High Temperature)	6	11/17/11



# CF34-8E Turbofan

## Technical Manual Index – May 1, 2021

### General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
73-45-18	CF34 ALL	RTV Application	6	11/17/11
73-50-00	CF34 ALL	Protective Coatings	6	11/17/11
73-50-16	CF34 ALL	Removal of Conformal Coatings	6	11/17/11
73-50-17	CF34 ALL	Recoating Conformal Coated Repaired Areas	9	09/01/16
73-50-18	CF34 ALL	Aluminum Surface Touch-up with Chromate Solution	6	11/17/11
73-50-19	CF34 ALL	Painted Surface Repair	6	11/17/11
73-60-00	CF34 ALL	Electrostatic Discharge Control	6	11/17/11
73-60-02	CF34 ALL	ESD Equipment Calibration	6	11/17/11
73-60-16	CF34 ALL	Handling ESDS Devices	6	11/17/11
73-61-00	CF34 ALL	Moisture Sensitive Devices	6	11/17/11
73-61-16	CF34 ALL	Moisture Sensitive Device Preparation	6	11/17/11
73-70-00	CF34 ALL	Flexible Circuit Card Assembly Repair	6	11/17/11



# CF34-8E Turbofan

## Technical Manual Index – May 1, 2021

### General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
73-70-16	CF34 ALL	Connector Removal and Replacement	6	11/17/11
73-80-00	CF34 ALL	Magnetic Media and Software	6	11/17/11
73-80-16	CF34 ALL	Media Storage Precautions	6	11/17/11
73-80-17	CF34 ALL	Record Keeping and Configuration Control	6	11/17/11
73-90-00	CF34 ALL	Electrical Wiring	6	11/17/11
73-90-16	CF34 ALL	Wiring and Cable Lacing	6	11/17/11
73-90-17	CF34 ALL	Crimped Electrical Connection	7	06/15/15
73-90-18	CF34 ALL	Shielded Wire Processes	6	11/17/11
73-90-19	CF34 ALL	Wire Preparation Processes	6	11/17/11
73-95-00	CF34 ALL	Chassis Repairs	6	11/17/11
73-95-19	CF34 ALL	Broken Screw Removal	6	11/17/11
73-95-20	CF34 ALL	Chassis Dent and Scratch Repair	6	11/17/11





GE Aviation

# CF34-8E Turbofan Technical Manual Index – May 1, 2021 General Practices Manual

GENERAL PRACTICES MANUAL SECTIONS ARE AVAILABLE FOR FIRST TIER CUSTOMERS UPON REQUEST. PLEASE SUBMIT YOUR REQUEST TO [aviation.fleetsupport@ge.com](mailto:aviation.fleetsupport@ge.com)

THE SECTIONS ARE REVISED INDIVIDUALLY. THE SECTIONS ARE ALSO AVAILABLE ON THE BAE WEBSITE OR FROM BAE BY CONTACTING:  
[cs-customer.service@baesystems.com](mailto:cs-customer.service@baesystems.com).

GEK 99373-	Engine Model	Nomenclature	Current Rev No.	Current Rev Date
73-95-21	CF34 ALL	Chassis Surface Weld Area Repair	6	11/17/11
73-95-22	CF34 ALL	Chassis Surfaces Repair	6	11/17/11
73-95-30	CF34 ALL	Aluminum Surface Repair by Chemical Weld Application	6	11/17/11
73-95-32	CF34 ALL	Threaded Insert Overhaul	7	04/22/14