QUALITY REMARK: AEPD QUALITY REQUIREMENT NUMBER 442 MRB REPAIR TYPE 111: REPAIR PROCEDURE FOR B50TF119 CLASS A COMBINED WITH P16TF3 CLASS B.

SUPPLIER TO SUBMIT THE FOLLOWING TO PURCHASER IN SHIPPING CONTAINER WITH PARTS PLUS DUPLICATE COPIES UNDER SEPARATE MAILING TO APPROPRIATE GE CONTRACT ADMINISTRATOR:

CERTIFICATE OF CONFORMNACE TO MRB REPAIR AND ALL APPLICABLE SPECIFICATIONS REFERENCED ON MRB REPAIR PROCEDURE AND PURCHASE ORDER. SAID CERTIFICATE SHALL INCLUDE DOCUMENTATION THAT PARTS WERE VISUALLY INSPECTED AND ACCEPTED BEFORE AND AFTER SPRAY FOR CHIPPING, FLAKING, CRACKING, OVERSPRAY, AND OTHER VISUAL DEFECTS.

DOCUMENTATION OF INSPECTION AND ACCEPTANCE OF TEST COUPONS IN ACCORDANCE WITH P16TF3 CLASS B.

COPY OF MRB REPAIR PROCEDURE WITH SUPPLIER QUALITY INSPECTOR OR REPRESENTATIVE SIGNATURE SIGN-OFF OR STAMP ON ALL APPLICABLE ITEMS ON MRB REPAIR PROCEDURE INDICATING COMPLETION OF AND COMPLIANCE TO ALL REQUIREMENTS.